

**ALLES PREISE NETTO ZZGL. VERSANDKOSTEN & ZOLLABWICKLUNG
REPARATURANFRAGEN BITTE AN FLORIAN@UL-GMBH.DE**

REPAIR ITEM	REPAIR DESCRIPTION	PRICE
R001-001	REPAIR - SV-D600 7" SkyView SE Display	€650,00
R001-002	REPAIR - SV-D900 10" SkyView SE Display	€650,00
R001-003	REPAIR - SV-D700 7" SkyView Display	€650,00
R001-004	REPAIR - SV-D1000 10" SkyView Display	€650,00
R001-005	REPAIR - SV-D1000T 10" SkyView Touch Display	€650,00
R001-006	REPAIR - SV-HDX800 7" SkyView HDX Display	€650,00
R001-007	REPAIR - SV-HDX1100 10" SkyView HDX Display	€650,00
R002-001	REPAIR - SV-ADAHRS-200/201 ADAHRS Module	€450,00
R002-002	REPAIR - SV-ARINC-429 ARINC 429 Module	€175,00
R002-003	REPAIR - SV-ADSB-470/472 ADS-B Traffic/WX Module	€350,00
R002-004	REPAIR - SV-EMS-220/221 Engine Monitoring Module	€250,00
R002-005	REPAIR - SV-MAG-236 Remote Magnetometer	€175,00
R002-006	REPAIR - SV-KNOB-PANEL Knob Control Panel	€175,00
R002-007	REPAIR - SV-AP-PANEL AP Control Panel	€175,00
R002-008	REPAIR - SV-AP-TRIMAMP Trim Motor Adapter	€190,00
R002-009	REPAIR - SV-COM-PANEL COM Control Panel	€175,00
R002-010	REPAIR - SV-COM-425 VHF COM Transceiver Module	€550,00
R002-011	REPAIR - SV-COM-760 VHF COM Transceiver Module	€450,00
R002-012	REPAIR - SV-COM-T25 VHF COM Transceiver Module	€550,00
R002-013	REPAIR - SV-COM-T8 VHF COM Transceiver Module	€550,00
R002-014	REPAIR - SV-XPNDR-261 Transponder	€750,00
R002-015	REPAIR - SV-XPNDR-262 Transponder	€750,00
R002-016	REPAIR - SV-INTERCOM-2S Two-Place Stereo Intercom	€190,00
R002-017	REPAIR - SV-GPS-2020 GPS Antenna/Receiver Module	€450,00
R002-018	REPAIR - SV-GPS-250 GPS Antenna/Receiver Module	€200,00
R002-019	REPAIR - Other	€100,00
R003-001	REPAIR - SV32/42/52 Servo	€275,00
R004-001	REPAIR - D3 Pocket Panel Portable EFIS	€300,00
R004-002	REPAIR - DRX Portable ADS-B Receiver	€300,00
R005-001	REPAIR - EFIS-D6	€850,00
R005-002	REPAIR - EFIS-D60	€850,00
R005-003	REPAIR - EFIS-D10A	€650,00
R005-004	REPAIR - EFIS-D100	€850,00
R005-005	REPAIR - EMS-D10	€850,00
R005-006	REPAIR - EMS-D120	€850,00
R005-007	REPAIR - FlightDEK-D180	€850,00
R005-008	REPAIR - D30 Touchscreen Electronic Flight Display	€650,00
R006-001	REPAIR - HS34 HSI Expansion Module	€300,00
R006-002	REPAIR - AP74 AP Interface Module	€300,00
R007-001	Functional Test - D10/D100 Series	€400,00
R007-002	Functional Test - SkyView Display or ADAHRS	€250,00
R007-003	Functional Test - Other	€150,00